
## Upgrade Lakeview/Beth El Cemetery Irrigation Systems

- ♦ Antiquated, 50-year-old, irrigation system:
  - ♦ Poor initial design
  - ♦ Decades of repairs upon repairs are failing
- ♦ Estimated Cost: \$3,090,372





# Gymnasium

- \* The City's Recreation court sports programs are not in control of their own programming because we have only two small gymnasiums; YACC and Pioneer Park Center. We rely heavily on the school district to use their gymnasiums. During the pandemic, City recreation was shut out of all school district gymnasiums.
- ♦ City Recreation court sport programs can not grow to meet the needs of the community without our own facilities.
- We serve several thousand participants each year for youth and adult court sports (volleyball, basketball, pickleball, dodgeball, number does not include all other sports and classes)



### The WHY...













# What's the Cost?

♦ Cost is estimated at: \$2,000,000



# Site Analysis/Conceptual Design for new Indoor/Outdoor Pool


- \* The City's only outdoor pool is nearly 70 years old! It has been "band-aided" many times over, however, the concrete pool shell is disintegrating—crumbling. The bath house and support facilities are also antiquated. Facility is not ADA accessible.
- \* Cheyenne is not meeting the needs of the "swimming" public. As an example, Casper has one indoor facility with 2 pools and 4 outdoor pools with a population of just over 57,000. This is 14.18 gallons of water/per person compared to Cheyenne's 6.55.
- Demand is high—the municipal pool has maxed out its available operational hours with recreational, educational, and fitness swim.
- Public support the public fought for the pool to be open during a pandemic. This is a healthy lifestyle community activity.
- A conceptual design and site analysis needs to be prepared for this project for an accurate cost estimate, analyze the best site, garner public input. The request is for \$250,000.

### Renovation of Dutcher Ballfield Complex

Dutcher 2019

**Dutcher Future** 





Currently 2 fields have lights, however the wood poles have rotted and the lights do not meet necessary illumination



New lights on all fields would double the amount of current use and provide necessary illumination



Current Backstops and fencing is worn and do not meet necessary height requirements for spectator safety.



Proper backstops and covered seating for spectators.



Current restrooms and concessions do not meet ADA requirements and are in disrepair.





#### Precast Restroom and Concession





# What's the Cost?

♦ Estimated Cost: \$7,527,517